

DVVP College of Engg
Vilad Ghat
Ahmednagar

Journal Voucher

No. : **372**


Dated : 27-Sep-2017

Particulars	Debit	Credit
Repair & Maint. Electrical <i>Dr</i>	2,350.00	
To Sahara Refrigeration & Airconditioner(TDS)		24.00
To Sahara Refrigeration & Airconditioner(Sr.Cr.)		2,326.00
New Ref 215 2,326.00 Cr		
	₹ 2,350.00	₹ 2,350.00

On Account of :

Electrical Maintanance air
Conditioner Reparing Bill
No. 215 As per DP No.88
Dated 06.09.2017




Authorised Signatory

Date : 06/09/2017

No.: 88

इले. मैटेनन्स विभाग

प्रती,

मा. प्राचार्य,

डॉ. विवेक पाटील अभियांत्रिकी महाविद्यालय, विक्रमधाम.

विषय - 'Board Room' मधील Air-Conditioner च्या Condenser Coil इंधली विलास मंजुरी मिळवून देणे.

संदर्भ - १) परवानगी क्र. ८२/दि. २५-०८-२०१७
२) कोटेशन क्र. २११/दि. १८-०८-२०१७

मा. मल्लिकार्जुन,


करील संदर्भित विषयास अनुषंगाने, आपले महाविद्यालयातील

'Board Room' मधील Air-Conditioner Outdoor Unit च्या Condenser Coil Breeding करून इंधली करण्याचे काम स. सागरा रेफ्रि. अँड एअर-कंडिशनिंग प्र. लार्. यांचेकडून करून घेतलेले आहे. तरी सोबत जोडलेल्या बिल नं. २१५/दि. ०१-०९-२०१७ प्रमाणे बिल मंजूर होण्यास मंजुरी मिळावी, ही विनंती.

① Air-Conditioner } ०२ } Rs. 1175 X 2 Nos = 2350/-
Condenser Coil } Job } [Two Thousand Three Hundred & Fifty Rs. Only.]
Breeding work }

आपला माहितीसाठी व पुढील कार्यावहारासाठी सविनय सादर.

आपला विश्वासू,


Elect. Engr

[Elect. Maint. Dept.]

Dr. Sanchuan
Transf. for n/a
Sanctioned
for n/a
for n/a

Date : 24/08/2017

82

No.:

इले. मटेनन्स विभाग

प्रती,

मा. प्राचार्य,

डा. विवेक पाटील अभियांत्रिकी महाविद्यालय, विक्रमाल:

विषय - 'Board Room' मधील Air-Conditioner च्या Condensor Coil दुर्दम्यते परवानगी मिळणेबाबत.

संदर्भ - 1) डी.पी. क्र. 37/म. 19-06-2017 ✓

2) डी.पी. क्र. 53/म. 11-07-2017.

मा. महोदय,

वरील संदर्भित विषयास अनुसरून आपले कॉलेजमधील 'Board Room' येथील 2.0 TR Tower Air-Conditioner च्या दोन्ही 'Condensor Coil' लिफ्टे मालत्यामुळे त्या बदललेल्या रु. 13,600/- खर्च अपेक्षित होत. परंतु, सदर Condensor Coil ला Breezing Point करलेल्या व A/C चे तात्पुरते संचलन होण्याकरिता पुढीलप्रमाणे खर्च करण्यास परवानगी मिळावी, ही विनंती.

① 2.0 TR Tower Air-Conditioner Condensor Coil checking of	} 02 } Rs. 2350/- Job
Repairing with Copper	
Breezing Point work करणे.	

[Two Thousand Three Hundred Fifty Rs. only]

Sanctioned for आपले भारतीराव व पुढील कार्यवाहीसव सविनय सादर.

आपला
24/8

Quotation No. 211
म. 18/08/2017

आपला विश्वासू,

Elect. Engr

[Elect. Maint. Dept.]

CASH / DEBIT

Quotation.

Near Mukund Stiel, Delight Furniture,
Tilak Road, Ahmednagar
Cell :- 9270814866, 9209599993

SAHARA

REFRIGERATION & AIRCONDITIONER

To, Dr. Vikhe Patil Engineering
College -
Ahmednagar.

No. **211**

Date 18 / 08 / 2017

Sr. No.	Description	Rate	Amount	
			Rs.	Ps.
①	2 OUT DOOR Condenser Coil Brazing Joint 02 Job Site -> Bord Room at Admin Block. Tested OK. <u>Sw</u> <u>mr. Nirmal 29/8/17</u>	1175/-	2350/-	
		Total	2350/-	

(Subject to Ahmednagar Jurisdiction)

SAHARA REFREGARETION
& AIR CONDITIONER SGF
TILAK ROAD, AHMEDNAGAR
For-SAHARA REFRIGERATION &
AIRCONDITIONER

Near Mukund Stiel, Delight Furniture,
Tilak Road, Ahmednagar
Cell :- 9270814866, 9209599993

SAHARA

REFRIGERATION & AIRCONDITIONER

To, Dr. Vikhe Patil Engineering
College -
Ahmadnagar.

No. **215**

Date 1 / 9 /2017

Sr. No.	Description	Date	Amount	
			Rs.	Ps.
①	2 OUT Door Condensor Coil Brazing Joint O2 Job Site → Bord Room at Admin Block Tested OK.	11751-	23501-	
		Total	23501-	

(Subject to Ahmednagar Jurisdiction)

**SAHARA REFRIGERATION
& AIR CONDITIONER**
TILAK ROAD, ALHAMBUR
**For SAHARA REFRIGERATION &
AIRCONDITIONER**